

From: [Miller, Garyg](#)
To: [Walters, Donn](#)
Cc: [Sanchez, Carlos](#)
Subject: San Jacinto Update
Date: Wednesday, April 20, 2016 3:45:00 PM

Donn,

The latest San Jacinto update for the site profile webpage is below.

Thanks,

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

SAN JACINTO RIVER WASTE PITS SUPERFUND SITE, CHANNELVIEW, TX: The San Jacinto River is undergoing major flooding now due to the recent rains. The current elevation (on April 20, 2016) at the Sheldon gauge station located about 5 miles upstream from the site is 15.39 feet. For reference, the National Weather Service considers river levels over 15 feet to be major flooding for the area. The EPA Dive Team began an underwater inspection of the temporary armored cap on April 4, 2016. The Dive Team inspection will be completed in May after river levels fall. The placement of pore water samplers at 14 locations within the temporary cap, surface water, fish tissue, and sediment sampling will also be delayed until flooding in the San Jacinto River subsides. The PRPs completed installation of seven of the eight planned ground water monitoring wells and installed the passive ground water samplers, which will be left in place for about 2 months to reach equilibrium. The last ground water monitoring well will be installed when the site can be accessed again. Finally, deployment of the lighted buoys will begin after the flood waters have receded. (Meyer, x6742)



9768528